

## Cluster Box Unit Accessories

### Florence Manufacturing Company

5935 Corporate Dr.  
Manhattan, KS 66503-9675  
Telephone: 800-275-1747  
785-323-4400

Fax: 800-275-5081 (toll-free)  
785-323-4470

[www.florencemailboxes.com](http://www.florencemailboxes.com)

Decorative CBU Accessories  
Vogue-Vogue C1 Crown Molding Cap  
Vogue-Vogue P114 Short Pedestal Cover  
Vogue-Vogue P128 Tall Pedestal Cover  
Regency — 1201, Tall Pedestal Cover  
Regency — 1202, Short Pedestal Cover  
Regency — 1200, Top Cover  
Regency — Flame & Ball, Top Cover Finials

**Note:** CBU accessories are optional equipment that is intended to enhance the aesthetic appearance of commercially purchased units.

## High Security Cluster Box Units

### Florence Manufacturing Company

5935 Corporate Dr.  
Manhattan, KS 66503-9675  
Telephone: 800-275-1747  
785-323-4400

Fax: 785-323-4470  
800-275-5081 (toll-free)

[www.florencemailboxes.com](http://www.florencemailboxes.com)

Unit is powder-coated aluminum and stainless steel.

Contract #1CDSEQ-11-B-1004 — Place orders through eBuy2.

#### **Note:**

- 1) You must use eBuy2 to purchase supplies from this contract supplier.
- 2) Unit is anodized, painted aluminum. Pedestal is anodized, painted stainless steel.

Contract No. 1CDSEQ-05-B-3001, available on eBuy2.

## Outdoor Parcel Locker (OPL)

### USPS-B-1116B

#### Florence Manufacturing Company

5935 Corporate Dr.  
Manhattan, KS 66503-9675  
Telephone: 800-275-1747  
785-323-4400

Fax: 800-275-5081 (toll-free)  
785-323-4470

[www.florencemailboxes.com](http://www.florencemailboxes.com)

Contract #1CDSEQ-11-B-1004 — Place orders through eBuy2.

**Note:** You must use eBuy2 to purchase supplies from this contract supplier.

## Replacement Pedestals — CBU, NDCBU, and OPL Universal

### Florence Manufacturing Company

5935 Corporate Dr.  
Manhattan, KS 66503-9675  
Telephone: 800-275-1747  
785-323-4400

Fax: 800-275-5081 (toll-free)  
785-323-4470

[www.florencemailboxes.com](http://www.florencemailboxes.com)

NDCBU Universal Pedestal is anodized aluminum — does not fit Superior units

Replacement Pedestal — OPL

Replacement Pedestal — American Locker CBU

Replacement Pedestal — American Locker OPL

Contract #1CDSEQ-05-B-3001 — Place orders through eBuy2.

**Note:** You must use eBuy2 to purchase supplies from this contractor.

## Wall-Mounted Centralized Mail Receptacles

### USPS-STD-4C

USPS-STD-4C was fully implemented on October 6, 2006. All new multi-unit constructions with building permits submitted before October 6, 2006, retain the option of using apartment-style receptacles built to the specifications of USPS-STD-4B+.

All multi-unit construction with building plans submitted on October 6, 2006, or later are required to use wall-mounted mail receptacles built and approved to the specifications of USPS-STD-4C.

The receptacles offer:

- Improved compartment security.
- Customer-friendly compartment designs, which allow mail to be placed flat into the compartment.
- Increased ease of use for carriers
- Larger customer compartment capacity for small parcels and rolls (SPRs), small parcels, and large volumes of mail.
- One parcel locker for every 10 customer compartment ratios for installations with 10 customer compartments or more.
- Secure outgoing mail compartments.

The use of USPS-STD-4C boxes is primarily intended for new construction and not as a means of retrofitting existing complexes. However, buildings undergoing significant renovations or rehabilitations may be required to convert to wall-mounted receptacles that are USPS-STD-4C compliant. If these renovations include significant struc-

tural changes and present an opportunity for more complete makeovers, the builders should include 4C receptacles. Buildings that are simply remodeling or changing the outward/surface appearance of the lobby are *not* considered examples of renovations that would trigger the use of 4C receptacles.

If you have additional questions, contact your area or district growth coordinators for further information, or send an e-mail to [www.wallmountedreceptacles@usps.gov](mailto:www.wallmountedreceptacles@usps.gov).

### Approved Manufacturers

#### USPS-STD-4C

##### 2BGlobal

16 Technology Dr., Ste. 172  
Irvine, CA 92618-2328  
Telephone: 800-650-2606  
949-502-3778

Fax: 949-502-3772

[www.2B-Globalmailboxes.com](http://www.2B-Globalmailboxes.com)

Front Loader Designs

1 & 2 High Customer Compartments

Largest Approved Double-Column Unit has 20  
(1 High) Customer Boxes

##### Bommer Industries, Inc.

PO Box +187  
Landrum, SC 29356-0187  
Telephone: 800-334-1654  
864-457-3301

Fax: 864-457-5370

[www.bommer.com](http://www.bommer.com)

Front Loader Designs

1 & 2 High Customer Compartments

Largest Approved Double-Column Unit has 20 (1 High)  
Customer Boxes

##### Florence Manufacturing Company

5935 Corporate Dr.  
Manhattan, KS 66503-9675  
Telephone: 800-275-1747  
785-323-4400

Fax: 800-275-5081 (toll-free)  
785-323-4470

[www.florencemailboxes.com](http://www.florencemailboxes.com)

Front Loader Designs

Rear Loader Designs

1, 2, 3, & 4 High Customer Compartments

Largest Approved Double-Column Unit has 20 (1 High)  
Customer Boxes

##### Jensen Mailboxes

105 Steel Craft Dr.  
Hartford, WI 53027-1631  
Telephone: 877-597-5671  
Fax: 800-991-6121

[www.jensenmailboxes.com](http://www.jensenmailboxes.com)

Front Loader Designs

1 & 2 High Customer Compartments

Largest Approved Double-Column Unit has 17 (1 High)  
Customer Boxes

##### Postal Products Unlimited

500 West Oklahoma Ave.  
Milwaukee, WI 53207-2649  
Telephone: 800-229-4500

[www.mailproducts.com](http://www.mailproducts.com)

Front Loader Designs

1 High Customer Compartments

Largest Approved Double-Column Unit has 20 (1 High)  
Customer Boxes

##### Salsbury Industries

1010 E. 62<sup>nd</sup> St.  
Los Angeles, CA 90001-1598  
Telephone: 800-624-5269

Fax: 800-624-5299

[www.mailboxes.com](http://www.mailboxes.com)

Front Loader Designs

Rear Loader Designs

1, 2, 3, & 4 High Customer Compartments

Largest Approved Double-Column Unit has 20 (1 High)  
Customer Boxes

##### Security Manufacturing Corp.

815 South Main St.  
Grapevine, TX 76051-5535  
Telephone: 800-762-6937  
817-329-1600

Fax: 817-481-3993

[www.securitymanufacturing.com](http://www.securitymanufacturing.com)

Front Loader Designs

1 High Customer Compartments

Largest Approved Double-Column Unit has 20 (1 High)  
Customer Boxes

### Apartment House Mail Receptacles — Horizontal and Vertical

**Note:** The Postal Service has revised USPS-STD-4B. The new standard is USPS-STD-4C.

For replacement of existing equipment, security enhanced versions of both horizontal and vertical boxes are now available. They are referred to as “USPS-STD-4B+” boxes and are designed to fit cleanly into buildings with old USPS-STD-4B boxes.

USPS-STD-4B+ boxes are approved for Postal Service mail delivery for existing indoor installations or existing protected outdoor locations. However, the Postal Service does not approve the purchase of this equipment for new installations and will not install Arrow locks in any such equipment. You may only order *replacement* parts for Postal Service–owned equipment that was installed in the past.